


West Goshen Township

East Goshen Township



Legend

- Municipal Boundary
- Parcel Boundary
- Study Area Boundary
- Chester County Health Department Records**
- Absorption Area Repair Permits Issued (124)¹
- Absorption Area Repair Permits Issued with BTG (3)²
- Non-Absorption Area Repair Permits Issued (22)³
- Permit Application Submitted Repair Feasibility Unresolved (17)⁴
- Permit Application Submitted Repair Infeasible (8)⁵
- System Pumping More Than Once Per Year (62)⁶

Notes:
 1. Repairs with no Best Technical Guidance (BTG).
 2. Use of BTG to reduce minimum isolation distances.
 3. Tank and delivery line repairs.
 4. Incomplete or passing soils testing with no follow-up.
 5. Failed soils testing and/or CCHD notes indicating unsuitable site.
 6. Based upon CCHD septage management database records for 2005 - May 2012.

Data Source:
 *Base data provided by Chester County GIS Department, May 2011
 *Septic Repair Permit Activity - Chester County Health Department, June 2012



**MAP II-1
 CHESTER COUNTY HEALTH
 DEPARTMENT RECORDS**

**WESTTOWN TOWNSHIP
 ACT 537 PLAN**
 Westtown Township, Chester County, Pennsylvania

URS
 Iron Hill Corporate Center
 Sabre Building Suite 300
 4051 Ogletown Road
 Newark, DE 19713

DATE:	July 2012
DRAWN BY:	RM
CHECKED BY:	SC