

Ashleigh Drive Photos



9-6-23

Ashleigh Drive (9.3% grade) approaching Kreidler Avenue. Grade maintained through the



intersection. 26' cartway.





Ashleigh Drive (10.4% grade) at Kreidler Avenue



Ashleigh Drive (10.4% grade) with horizontal and vertical curvature on the roadway

Ashleigh Drive (10.4% grade) with horizontal curvature and vertical curvature on the roadway